

OREGON RPS CERTIFICATION PROCESS

1. Review the following summary of the Oregon RPS to check eligibility.
www.oregon-rps.org/ENERGY/RENEW/docs/Oregon_RPS_Summary_Oct2007.pdf
2. Become a WREGIS Account Holder or - rarely - have your GU registered under another AH (aggregator, utility, etc.). www.wregis.org
3. Register the facility as a Generating Unit (GU) in WREGIS.
4. If you've done steps 2 & 3, please inform the Oregon Department of Energy's Kip Pheil.
5. Otherwise, once you start the GU registration process please inform Kip.
(Kip Pheil's contact information- office phone number 503-378-4442 or e-mail address kip.pheil@state.or.us. Kip will ask that you send him the "Static Data" for the GU (and explain what it is if need be).
6. He will then enter an OR Certification number for your GU after I've confirmed your eligibility.

If you have more questions please contact Kip Pheil at 503-378-4442.