


I-84 Traffic Barrier Upgrades (K19928)



Roadside Improvement Scope Summary

63 roadside sites improved
 Roadside barrier improved from MP 64-152
 8056 ft. of substandard guardrail removed
 860 ft. of substandard barrier removed
 55 guardrail end treatments installed
 11,190 ft of guardrail installed
 809 ft. of barrier installed

Legend

- Roadside barrier improvements
- Bridge rail retrofits
- Bridge rail protective screening

Locations for K19928: I-84: Traffic Barrier Upgrades

BRIDGE	HIGHWAY	ROUTE	MP BEGIN	MP END	LENGTH	COUNTY	REG	SCOPE
02133A	002 COLUMBIA RIVER	I-84	104.76	104.76	0	SHERMAN	4	RAIL RETROFIT
09232	002 COLUMBIA RIVER	I-84	109.76	109.79	0.03	SHERMAN	4	RAIL RETROFIT
09232A	002 COLUMBIA RIVER	I-84	109.76	109.79	0.03	SHERMAN	4	RAIL RETROFIT
09225	002 COLUMBIA RIVER	I-84	109.95	109.95	0	SHERMAN	4	RAIL RETROFIT
09225A	002 COLUMBIA RIVER	I-84	109.95	109.95	0	SHERMAN	4	RAIL RETROFIT
08805	002 COLUMBIA RIVER	I-84	85.51	85.51	0	WASCO	4	SCREENING
08944	002 COLUMBIA RIVER	I-84	123.31	123.31	0	GILLIAM	4	SCREENING
09198	052 HEPNER	I-84	0.29	0.34	0.05	GILLIAM	4	SCREENING